

Mainline 6B 2012 Maintenance and Rehabilitation & Line 6B Replacement Projects
IDEM Water Quality Certification Independent Environmental Monitor Weekly Observation Report

Observation Dates:	03/24/14 thru 03/29/14
IEM Name:	Eric Sorenson
Waterbody Identification Number(s):	S-488-Y, S-489-A, S-489-Z, S-488-B, S-486-A, S-493-D, S-495-B
Wetland Identification Number(s):	W-488-Y, W-489-A, W-489-C, W-493-Z, W-495-A1
Enbridge Land Tract Identification Number(s):	N-622-6, N-623-1A, N-622-9, N-623-2, N-620-4-1, N-626-7, N-626-5A-1
County(s): St.Joseph, LaPorte, Porter	Porter and LaPorte
<p>03/24/14: No activity on ROW. ECD'S are in working order. 03/25/14: No activity on ROW. ECD'S are in working order. 03/26/14: No activity on ROW. ECD'S are in working order. 03/27/14: No activity on ROW. ECD'S are in working order. 03/28/14: Performed storm water inspections. Silt fence in need of repair at sta#1660+00. The environmental group has been made aware of this issue. 03/29/14: Performed storm water inspections. No issues found.</p>	



sta#1126+00_MP486.5_S-486-A_ECD'S in working order_E



sta#1126+00_MP486.5_S-486-A_ECD'S in working order_E



sta#1505+00_MP493.6_ECD'S in working order_N



sta#1660+00_MP496.6_ECD down Punch list item_NE



sta#1228+00_MP488.4_W488-Y_ECD'S in working order_NE



sta#1585+00_MP495.1_W-495-A1_ECD'S in working order_E



